

WIPP SHIPMENT LEVEL VI INSPECTION POLICIES BY STATE

STATE	Level 6 Inspection Policy
Arizona	Arizona reserves the right to conduct CVSA Level VI inspections on WIPP shipments entering Arizona. Due to the remote location of the port of entry some of the inspections will be conducted near the city of Flagstaff. At this time, Arizona does not have plans to conduct CVSA Level VI inspections on a regular basis.
California	The California Highway Patrol (CHP) plans to conduct CVSA Level VI inspections on WIPP shipments under the following guidelines: 1) For shipments originating within California such as Lawrence Livermore Nuclear Laboratories (LLNL). 2) For WIPP shipments originating in another state, that entered California, the CHP will decide on a case-by-case basis when to conduct a CVSA Level VI inspection at the originating point of entry into California. 3) A CVSA Level VI inspection will be conducted on every highway route controlled quantity (HRCQ) shipment of radioactive material with a California point-of-origin. 4) A CVSA Level VI inspection will also be conducted at any time deemed necessary by CHP personnel.
Colorado	All WIPP shipments entering Colorado will have a CVSA inspection conducted at the Port-of- Entry.
Idaho	Idaho will complete a CVSA Level VI inspection at the point of origin and point of destination on all TRU waste shipments in and out of Idaho. Idaho reserves the right to complete en-route inspections on those shipments traveling across Idaho. Idaho will complete point of destination and point of origin inspections on other shipments in Idaho such as Foreign Fuels and other shipments into or out of INEEL.
Nebraska	Nebraska will honor a CVSA sticker that is current, thereby eliminating the need to conduct another inspection of the vehicle. Unless equipment defects are noted, Nebraska chooses to keep the vehicle moving. If defects are noted, the vehicle breaks down, or is involved in a collision; Nebraska reserves the right to conduct a Level VI inspection.
Nevada	Nevada conducts a Level VI inspection on every WIPP shipment originating at the Nevada Test Site.
New Mexico	New Mexico conducts a Level VI inspection on all WIPP shipments originating in New Mexico are given CVSA Level VI inspections at the point of origin. Certain WIPP shipments entering New Mexico are given a CVSA Level VI inspection at the New Mexico Port-of-Entry.
Oregon	Oregon conducts random inspections of WIPP shipments from Hanford as they enter the state at Umatilla. The CVSA Level VI inspections are conducted by inspectors from the Oregon Department of Transportation. Oregon otherwise honors Level VI point-of-origin inspections conducted by the State of Washington.
Utah	Utah will honor valid CVSA stickers. Utah reserves the right to conduct CVSA Level VI inspections on WIPP shipments entering Utah if deemed necessary. At this time, Utah does not conduct CVSA Level VI inspections on a regular basis, but maintains two certified inspectors.
Washington	Washington will conduct CVSA Level VI inspections on all WIPP shipments originating at Hanford. Washington will also conduct CVSA Level VI inspections on all Radioactive loads entering Washington.
Wyoming	Wyoming reserves the right to conduct CVSA Level VI inspections on WIPP shipments entering Wyoming. At this time, Wyoming does not have plans to conduct CVSA Level VI inspections on a regular basis.